CONNECT CLAMP ASSEMBLY 229



Assembly Service

item	Order No.
Clamps assembled on a hose without adapter	229-0000-0000
adapter assembled on a hose with clamps	229-0000-0001
Sleeve assembled on a hose	229-0000-0002

Overpressure and underpressure are recommended threshold operating values, products can be subjected to higher loads upon request. The bending radius is measured through the inside of the hose arch. The right to make technical modifications is reserved. All values determined at 20 °C and are approx. data. Additional information at www.norres.com/en/technology/.